

AD-A107 589

TIPPETTS-ABBETT-MCCARTHY-STRATTON NEW YORK
NATIONAL DAM SAFETY PROGRAM. STILL LAKE DAM (INVENTORY NUMBER N--ETC(U)
AUG 81 E O'BRIEN


F/G 13/13

DACW51-81-C-0008

NL

UNCLASSIFIED

1 of 1
AD
A107589



END
DATE
FILMED
1-82
DTIC

AD A107589

LONG ISLAND BASIN

STILL LAKE DAM

WESTCHESTER COUNTY, NEW YORK
INVENTORY NO. N.Y. 1266

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM



APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED

NEW YORK DISTRICT CORPS OF ENGINEERS

JULY 1981

DTIC
ELECTE
NOV 16 1981
S D D

81 11 13 084

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. AD-A107589	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report Still Lake Dam Long Island Basin, Westchester County, NY Inventory No. 1266		5. TYPE OF REPORT & PERIOD COVERED Phase I Inspection Report National Dam Safety Program
7. AUTHOR(s) EUGENE O'Brien		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS Tippett's-Abbott-McCarthy-Stratton The TAMS Building 655 Third Avenue New York, New York 10017		8. CONTRACT OR GRANT NUMBER(s) DACW51-81-C-0008
11. CONTROLLING OFFICE NAME AND ADDRESS Department of the Army 26 Federal Plaza New York District, CofE New York, New York 10287		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
13. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) Department of the Army 26 Federal Plaza New York District, CofE New York, NY 10287		12. REPORT DATE 5 August 1981
		13. NUMBER OF PAGES
		14. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
15. DISTRIBUTION STATEMENT (of this Report) Approved for public release; Distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
13. SUPPLEMENTARY NOTES		
13. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety National Dam Safety Program Visual Inspection Hydrology, Structural Stability Still Lake Dam Westchester County Long Island Basin		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report provides information and analysis on the physical condition of the dam as of the report date. Information and analysis are based on visual inspection of the dam by the performing organization. Phase I investigation of Still Lake Dam did not indicate conditions which constitute an immediate hazard to human life or property. The project, however, does have inadequacies and deficiencies which, if not remedied, have the potential for developing into hazardous conditions.		

Using the Corps of Engineers screening criteria for review of spillway adequacy, it has been determined that the spillway is inadequate for all floods in excess of 4 percent of the Probable Maximum Flood (PMF). Overtopping of the dam would significantly increase the hazard to loss of life and property, and therefore, the spillway is adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream of the dam.

Structural stability analyses based on available information and the visual inspection indicates that the stability of the spillway section against overturning is inadequate for all loading conditions except earthquake, whereas sliding is inadequate for all loading conditions.

The seepage condition which exists on the surfaces and downstream of the earth buttress should be investigated to determine its cause, the stability of the structure under the seepage forces, and to provide remedial measures.

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special

DTIC
ELECTE
S NOV 16 1981 **D**
D

LONG ISLAND BASIN

STILL LAKE DAM

**WESTCHESTER COUNTY, NEW YORK
INVENTORY NO. N.Y. 1266**

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



NEW YORK DISTRICT CORPS OF ENGINEERS

JULY 1981

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C., 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, and analyses involving topographic mapping, sub-surface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
STILL LAKE DAM
I.D. NO. N.Y. 01266
DEC. NO. 214B-819
HUDSON RIVER BASIN
WESTCHESTER COUNTY, N.Y.

CONTENTS

	<u>Page No.</u>
- ASSESSMENT	-
- OVERVIEW PHOTOGRAPH	-
1 PROJECT INFORMATION	1
1.1 GENERAL	1
a. Authority	1
b. Purpose	1
1.2 DESCRIPTION OF THE PROJECT	1
a. Description of the Dam and Appurtenant Structures	1
b. Location	2
c. Size Classification	2
d. Hazard Classification	2
e. Ownership	2
f. Purpose	2
g. Design and Construction History	2
h. Normal Operating Procedure	2
1.3 PERTINENT DATA	3
a. Drainage Area	3
b. Discharge at Damsite	3
c. Elevation	3
d. Reservoir	3
e. Storage	3
f. Reservoir Surface	3
g. Dam	3
h. Reservoir Drain	3
i. Spillway	4
2 ENGINEERING DATA	5
2.1 GEOLOGY	5
2.2 SUBSURFACE INVESTIGATIONS	5
2.3 DESIGN RECORDS	5
2.4 CONSTRUCTION RECORDS	5

	<u>Page No.</u>
2.5 OPERATION RECORDS	5
2.6 EVALUATION OF DATA	5
3 VISUAL INSPECTION	6
3.1 FINDINGS	6
a. General	6
b. Dam	6
c. Spillway Section	7
d. Appurtenant Structures	7
e. Reservoir	7
f. Abutments	7
3.2 EVALUATION OF OBSERVATIONS	7
4 OPERATION AND MAINTENANCE PROCEDURES	9
4.1 PROCEDURES	9
4.2 MAINTENANCE OF DAM	9
4.3 WARNING SYSTEM IN EFFECT	9
4.4 EVALUATION	9
5 HYDROLOGIC/HYDRAULIC	10
5.1 DRAINAGE AREA CHARACTERISTICS	10
5.2 ANALYSIS CRITERIA	10
5.3 SPILLWAY CAPACITY	10
5.4 RESERVOIR CAPACITY	10
5.5 FLOODS OF RECORD	10
5.6 OVERTOPPING POTENTIAL	10
5.7 EVALUATION	11
6 STRUCTURAL STABILITY	12
6.1 EVALUATION OF STRUCTURAL STABILITY	12
a. Visual Observations	12
b. Design and Construction Records	12
c. Operating Records	12
d. Post-Construction Changes	12
6.2 STRUCTURAL STABILITY ANALYSIS	12

		Page No.
7	ASSESSMENT/RECOMMENDATIONS	14
7.1	ASSESSMENT	14
a.	Safety	14
b.	Adequacy of Information	14
c.	Need for Additional Investigations	14
d.	Urgency	15
7.2	RECOMMENDED MEASURES	15

APPENDICES

- A. DRAWINGS
- B. PHOTOGRAPHS
- C. VISUAL INSPECTION CHECKLIST
- D. HYDROLOGIC DATA AND COMPUTATIONS
- E. STABILITY ANALYSIS
- F. REFERENCES

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

NAME OF DAM	Still Lake Dam, N.Y. 01266
STATE LOCATED	New York
COUNTY LOCATED	Westchester
STREAM	Unknown
BASIN	Lower Hudson River
DATE OF INSPECTION	17 March 1981

ASSESSMENT

Phase I investigation of Still Lake Dam did not indicate conditions which constitute an immediate hazard to human life or property. The project, however, does have inadequacies and deficiencies which, if not remedied, have the potential for developing into hazardous conditions.

Using the Corps of Engineers screening criteria for review of spillway adequacy, it has been determined that the spillway is inadequate for all floods in excess of 4 percent of the Probable Maximum Flood (PMF). Overtopping of the dam would significantly increase the hazard to loss of life and property, and therefore, the spillway is adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary

computations, there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam would take place, significantly increasing the hazard to loss of life downstream of the dam.

Structural stability analyses based on available information and the visual inspection indicates that the stability of the spillway section against overturning is inadequate for all loading conditions except earthquake, whereas sliding is inadequate for all loading conditions.

The seepage condition which exists on the surfaces and downstream of the earth buttress should be investigated to determine its cause, the stability of the structure under the seepage forces, and to provide remedial measures.

It is therefore recommended that within 3 months of notification to the owner, detailed hydrologic/hydraulic investigations of the structure should be undertaken to more accurately determine the site specific characteristics of the watershed and their affect upon the overtopping potential of the dam. The results of these investigations will determine the appropriate remedial measures which will be required to achieve a spillway capacity adequate to discharge the outflow from at least the one-half (1/2) PMF event. Within 12 months of the date of notification to the owner, modifications to the structure, deemed necessary as a result of studies, should have been completed. At the same time, a detailed investigation of the structural stability of the spillway and the seepage condition and subsequent analysis should be performed. In the interim, a detailed emergency action plan must be developed and implemented during periods of unusually heavy precipitation. Also, around-the-clock surveillance of the structure must be provided during these periods.

In addition, the dam has other problem areas which, if left uncorrected, have the potential for the development of hazardous conditions and must be corrected within one year. These areas are:

1. Monitor at biweekly intervals with the aid of weirs and/or other measuring devices, the seepage occurring on the surfaces and downstream of the earth buttress.
2. Remove heavy brush, shrubs, trees and debris from the surfaces of the downstream earth buttress. Provide a program of periodic cutting and mowing of all embankment surfaces.


3. Place riprap or boulders at the toe of the spillway chute to provide proper energy dissipation and prevent erosion and undermining.

4. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of the reservoir drain and its control facilities. Document this information for future reference. The aforementioned emergency action plan should be maintained and updated periodically during the life of the structure.



Eugene O'Brien, P.E.
New York No. 29823

Approved by:



Col. W.M. Smith, Jr.
New York District Engineer

05 AUG 1981

Date:



OVERVIEW

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
STILL LAKE DAM
I.D. NO. N.Y. 01266
HUDSON RIVER BASIN
WESTCHESTER COUNTY, N.Y.

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority

The Phase I inspection reported herein was authorized by the Department of the Army, New York District, Corps of Engineers Contract No. DACW 51-81-C-0008 in a letter dated 14 December 1980 in fulfillment of the requirements of the National Dam Inspection Act, Public Law 92-367, dated 8 August 1972.

b. Purpose

This inspection was conducted to evaluate the existing conditions of the dam, to identify deficiencies and hazardous conditions, to determine if these deficiencies constitute hazards to life and property, and to recommend remedial measures where required.

1.2 DESCRIPTION OF THE PROJECT

a. Description of the Dam and Appurtenant Structures

Still Lake Dam is a stone/masonry gravity structure with upstream and downstream earth buttresses. The combined crest width of the gravity structure and the downstream earth buttress is 10.5 feet. The top of the upstream buttress is 3.5 feet below the gravity crest, and is of unknown width and shape. The maximum structural height of the dam is 16 feet.

The dam is about 540 feet long and consists of three linear segments: the right, the center and the left segment. The length of each segment is 200 feet, 20 feet and 320 feet, respectively. The segments are connected and form a "dog-leg" type configuration.

The downstream earth buttress has a grassed downstream slope, approximately 1V:2H (vertical to horizontal). The upstream buttress is unprotected and has an approximate 1V:6H slope extending an unknown distance upstream of the centerline.

The overflow section of the dam is an uncontrolled stone masonry structure about 15 feet in height located about 60 feet from the right abutment contact. The top of the spillway is a broad-crested concrete sill, 9.5 feet long and 3.5 feet wide.

Above the sill is a thin concrete arched bridge; at its maximum point, the bottom of the arch is 1.5 feet above the sill crest. The downstream face of the spillway consists of 12 steps, each approximately one foot high and wide. A concrete chute, approximately 30 feet long, is located at downstream edge of the structure.

A 24-inch steel pipe serves as a reservoir drain for the project. The drain is located beneath the spillway structure and is controlled by a valve located about two feet upstream of the crest of the dam and operated by a rotating T-bar control.

Discharge over the spillway and through the drain enter into the same downstream discharge channel. The channel is located at downstream edge of the chute, and extends perpendicular to the dam for its first 200 feet, wherein it follows a circuitous path.

b. Location

The dam is located in Ossining, Westchester County, New York. The dam is located approximately four miles northeast of the City of Ossining.

c. Size Classification

The dam has a structural height of 16 feet and a reservoir storage capacity of 150 acre-feet. The dam is classified as "small" in size (50 to 1,000 acre-feet).

d. Hazard Classification

The dam is classified as "high" hazard due to the number of homes located downstream; two of these homes are less than 200 feet downstream of the dam.

e. Ownership

The dam is owned and operated by the Still Water Lake Association. The President of the Association is Mr. Barry Shainman, Adams Road, Ossining, New York, 10562, Telephone No. (914) 762-1180.

f. Purpose

Still Lake Dam creates a recreational pool for use by members of the Association.

g. Design and Construction History

The dam was constructed about 1930. No information is available regarding its design and construction history.

h. Normal Operating Procedure

Water release from the lake is uncontrolled through the broad-crested sill. According to Mr. Saltzman, the Association representative who was present during this inspection,

the reservoir drain is operated when the need arises, and usually in the fall to allow for collection of spring runoff.

1.3 PERTINENT DATA

a.	<u>Drainage Area</u> , Square Miles	0.22
b.	<u>Discharge at Damsite</u> , cfs	
	Maximum Known Flood at Damsite	Unknown
	Spillway: Maximum Pool	30
	Reservoir Drain: Maximum Pool (Top of Dam)	Unknown
c.	<u>Elevation</u> , USGS Datum (MSL)	
	Maximum Pool	487 feet
	Normal Pool	486 feet
	Spillway Concrete Sill	486 feet
d.	<u>Reservoir</u>	
	Length of Maximum Pool	1600+ feet
	Length of Normal Pool	1600 feet
e.	<u>Storage</u>	
	Maximum Pool	177 acre-feet
	Normal Pool	150 acre-feet
f.	<u>Reservoir Surface</u>	
	Maximum Pool	26.2 acres
	Normal Pool	24.3 acres
g.	<u>Dam</u>	
	Type	Gravity Structure with Upstream and Downstream Earth Buttresses
	Length	540
	Height	16 feet
	Crest Width: Total	10.5 feet
	Concrete	2.5 feet
	Downstream Earth Buttress	8 feet
	Earth Buttress Slopes:	
	Downstream, (V:H)	1:2
	Upstream	Unknown
h.	<u>Reservoir Drain</u>	
	Type	Steel Pipe
	Diameter	24-Inch
	Closure	Valve

i. Spillway
Type

Height
Width
Location
Side Walls

Uncontrolled, Stone/
Masonry Stepped
Structure with Broad-
Crested Sill
16 feet
3.5 feet
60 feet from Right
Abutment Contact
Stone/Masonry

SECTION 2- ENGINEERING DATA

2.1 GEOLOGY

Still Lake Dam is located in the New England Upland Section of the New England Maritime Physiographic Province⁽⁴⁾. The bedrock in this section consists of metamorphic, igneous and sedimentary rocks which have undergone a complex sequence of deposition, folding, faulting and erosion. In the vicinity of the damsite, the rock comprises schistose gneiss of Precambrian Age⁽⁵⁾. The local relief is that of a maturity dissected peneplain modified by continental glaciation.

2.2 SUBSURFACE INVESTIGATIONS

No subsurface information is available for the project. The soil deposits which exist in the vicinity of the damsite are primarily glacial tills deposited during the Late Pleistocene Age. The till is composed primarily of gravels, silts and sands.

2.3 DESIGN RECORDS

No design records are available for the project.

2.4 CONSTRUCTION RECORDS

No construction records are available for the project.

2.5 OPERATION RECORDS

No operation records exist for the project.

2.6 EVALUATION OF DATA

There are neither design records nor construction records, however information obtained from personal interviews and observation made during the visual inspection are considered adequate for Phase I inspection.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

a. General

A visual inspection of Still Lake Dam was made on 17 March 1981. The weather was clear and sunny and the temperature was in the mid-fifties (°F). At the time of this inspection, the reservoir level was approximately two feet below the crest of the dam.

b. Dam

The exposed concrete surfaces of the dam appear to be in good condition; no structural cracking or deterioration was observed (See OVERVIEW). The vertical and horizontal alignment of the gravity crest and the downstream earth buttress crest are good. The alignment of the submerged upstream buttress crest could not be determined.

The surfaces of the downstream buttress contain debris, boulders, fallen trees and vegetation consisting of small bramble bushes to trees of large diameter (24-inch) (See PHOTOGRAPH 1). No surface cracking, movement at the toe or other signs of instability were observed along these surfaces.

The crest of the upstream earth buttress was, at the measured locations, 3.5 feet below the gravity crest. The submerged upstream slope was about 1V:6H, up to 15 feet from the exposed vertical upstream face of the gravity structure. According to Mr. Saltzman, there is a sharp drop in the lake bottom (or upstream buttress slope) approximately 20 feet upstream of the gravity crest.

Swamp-like vegetation and wet ground were observed along the surfaces of the downstream earth buttress and up to 40 feet downstream of the buttress toe. This condition appeared to occur along the entire length of the dam (See PHOTOGRAPHS 2, 3 and 4). In addition, an approximate 15 foot wide by 40 foot long wet area was observed near the right abutment contact. Channels have been constructed along the downstream toe by local residents to collect the seepage. In addition, a 4-inch diameter vitrified clay pipe was installed along the toe of the right buttress (to the right of the spillway section) to collect seepage in that area. This pipe discharges into the downstream spillway channel; the flow was measured to be 1+ gpm and the water was clear. No boils or other evidence of high water pressures were observed.

There is no emergency action plan for the project.

c. Spillway Section

The condition of the stone/masonry downstream steps and concrete chute is good (See PHOTOGRAPHS 6 and 7). There has been little to no deterioration; the stone appears durable and resistant to erosion and weathering. No leaks were observed through the structure. The spillway concrete sill and arch show minor signs of distress (See PHOTOGRAPH 8). The upstream surface of the spillway section could not be observed due to the existence of the upstream earth buttress. The downstream stone/masonry sidewalls appear to be in good condition (See PHOTOGRAPH 6).

d. Appurtenant Structures

The reservoir drain was not operated during this inspection, since Mr. Saltzman was unfamiliar with the valve operation. It is reported, however, that this valve is operational. No maintenance of the drain control facilities were reported.

The exposed downstream portion of the reservoir drain appears to be in good condition. The downstream channel contains small-size riprap along its sides and some vegetation (See PHOTOGRAPH 7). The area adjacent to the channel is relatively flat. Two homes exist along the banks of the channel within its first 200 feet downstream of the dam. Little or no riprap exists within the channel at the downstream edge of the spillway apron (See PHOTOGRAPH 9).

e. Reservoir

Still Lake is bordered by the Taconic State Parkway to the east and Pines Bridge Road to the south.

There are no visible signs of instability or sedimentation problems in the reservoir area.

f. Abutments

A relatively large wet area, as previously reported, was located near the right abutment contact.

3.2 EVALUATION OF OBSERVATIONS

The seepage condition which was observed requires immediate investigation to determine the extent of corrective action which is required. The following summarizes this condition as well as those previously reported, in order of importance, along with appropriate remedial action:

1. The seepage occurring along the downstream slope, at the toe and downstream of the toe, and near the left abutment contact, must be investigated immediately. Construction of weirs and monitoring of flow at biweekly intervals should be performed to determine the nature and extent of this seepage.

2. Heavy brush, shrubs, trees and debris should be cut and/or removed from the surfaces of the downstream earth buttress. A program of periodic cutting and mowing should be initiated. Inspections should be made to determine if removal and/or cutting of vegetation will adversely affect the condition of the dam.

3. Riprap or boulders should be placed at the toe of the spillway chute.

4. The reservoir drain and its control facilities should be inspected and maintained on a yearly basis. This information should be documented for future reference.

5. Provide a program of periodic inspection and maintenance of the dam and appurtenances including yearly operation and lubrication of the reservoir drain at its control facilities. Document this information for future reference. Develop an emergency action plan.

SECTION 4 - OPERATION AND MAINTENANCE PROCEDURES

4.1 PROCEDURES

No written operation and maintenance procedures exist for the project. It is reported that the reservoir drain is operated when the need arises, and usually in the fall to allow for storage or spring runoff.

4.2 MAINTENANCE OF DAM

It is reported that the dam is not maintained on a regular basis. No formal maintenance program or manual exists for the project.

4.3 WARNING SYSTEM IN EFFECT

No warning system is either in effect or preparation.

4.4 EVALUATION

The dam and appurtenances have not been adequately maintained, as evidenced by the seepage problems reported in "SECTION 3 - VISUAL INSPECTION".

SECTION 5 - HYDROLOGIC/HYDRAULIC

5.1 DRAINAGE AREA CHARACTERISTICS

Still Lake Dam is located northeast of Ossining in New Castle Township, Westchester County, New York (Hydrologic Unit Code 02030101) at the intersection of the Taconic Parkway and Pines Bridge Road. The drainage area contributing to the lake is 140.5 acres (0.22 square miles) of wooded gently sloping terrain with relatively little development. The lake occupies approximately 17 percent of the drainage area.

5.2 ANALYSIS CRITERIA

The analysis of the capacity of the service spillway was performed using the HEC-1DB computer program⁽¹⁾. A unit hydrograph was developed using Snyders coefficient of $C_T = 2$ and $640 C_p = 325$. The all season Probable Maximum Precipitation for 200 square miles in 24 hours of 22 inches was obtained from the Weather Bureau's Hydrometeorological Report No. 33 and distributed over 48 hours⁽²⁾. In accordance with the "Recommended Guidelines for Safety Inspection of Dams"⁽³⁾, the adequacy of the spillway was analyzed using the Probable Maximum Flood (PMF).

5.3 SPILLWAY CAPACITY

The principal spillway of Still Lake Dam is 9.5 feet in length with a crest elevation of 486, 1.0 feet below the top of the dam. The spillway is assumed to act as a broad-crested weir and the computed maximum discharge with a head of 1.0 feet is 30 cfs.

5.4 RESERVOIR CAPACITY

The normal capacity of Still Lake is listed as 150 acre-feet with 27 acre-feet of surcharge storage, which is equivalent to about 2.3 inches of runoff over the entire basin.

5.5 FLOODS OF RECORD

There are no records available of floods or maximum lake elevations; however, it is reported that the dam has never been overtopped.

5.6 OVERTOPPING POTENTIAL

The potential of the dam being overtopped was investigated on the basis of the spillway discharge capacity and the available surcharge storage to meet the selected design flood inflows.

The computed PMF, routed through the lake resulted in a maximum lake elevation of 487.54 feet, 0.54 feet above the top of the dam. Duration of flow over the dam was 12.3 hours, and the peak outflow was 718 cfs. One-half (1/2) the PMF raised the lake elevation to 487.32 feet with a peak discharge of 351 cfs. Lake elevation was assumed to be 486 (spillway crest elevation) at the start of the flood event.

A summary of the HEC-1DB multi-plan analysis is listed below.

<u>RATIO OF PMF</u>	<u>PEAK INFLOW (cfs)</u>	<u>PEAK OUTFLOW (cfs)</u>	<u>MAXIMUM DEPTH OVER DAM (ft)</u>
1.00	729	718	0.54
0.75	546	535	0.44
0.50	364	351	0.32
0.25	182	133	0.15

5.7 EVALUATION

The Still Lake Dam spillway is capable of discharging only 4 percent of the PMF without the dam being overtopped. The overtopping could cause the failure of the dam thus significantly increasing the hazard to the loss of life downstream. Therefore, the spillway is assessed as being "seriously inadequate".

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations

Visual observations did not indicate conditions which are an immediate hazard to life and property. However, the seepage condition which exists on the surfaces and downstream of the downstream earth buttress should be investigated to determine its cause, the stability of the dam and to provide remedial action. Although it is not an immediate hazard to life and property, if left uncorrected, this condition is potentially hazardous to life and property downstream of the dam.

b. Design and Construction Records

No design drawings, construction records or other pertinent project information is available for the project.

c. Operating Records

No operating records are kept for the project.

d. Post-Construction Changes

No post-construction changes have been reported.

e. Seismic Stability

In accordance with recommended Phase I guidelines, the dam is located in Seismic Risk Zone 1. However, based on local seismic experience, the New York State Geological Survey recommends that the damsite is to be considered in Zone 2. Therefore, the stability of the spillway was determined using a seismic coefficient of 0.05g.

6.2 STRUCTURAL STABILITY ANALYSIS

Since there are no design drawings for the project, the geometry of the spillway section for stability analyses was based on visual observations and engineering judgment. In addition the analysis was performed in accordance with the Corps of Engineers guidelines (Ref. 3). A detailed sketch along with stability computations is presented in Appendix E. A description of the cases examined and a summary of the results of the analyses are presented below.

<u>Case</u>	<u>Description of Loading Conditions</u>
1	Normal Loading, Lake Level at El 486, No Tailwater, Full Uplift
2	Same as Case 1, with 5 K/LF, Ice Load
3	Unusual Loading, 1/2 PMF, Lake Level at 486.32, Tailwater 1.7 Feet.

<u>Case</u>	<u>Description of Loading Conditions</u>
4	Extreme Loading, Full PMF, Lake Level at 486.52, Tailwater 2.4 Feet
5	Unusual Loading, Case 1 with Earthquake Loading (Zone 1, $n = 0.05$)

SUMMARY OF RESULTS

<u>Case</u>	<u>Location of Resultant</u>	<u>Sliding Factor of Safety</u>
1	0.34ft Outside Middle Third	1.63
2	6.77ft Outside Middle Third	1.13
3	1.53ft Outside Middle Third	1.43
4	1.77ft Outside Middle Third	1.40
5	Within Base	1.37

The results of the stability analysis indicate that the stability of the section analyzed is inadequate in overturning except for earthquake loading, and inadequate in sliding for all loading conditions. The configuration of the gravity spillway structure and the upstream earth buttress should be determined to more accurately evaluate the stability of the structure. After obtaining this information, an in-depth structural stability analysis should be conducted.

SECTION 7 - ASSESSMENT/RECOMMENDATIONS

7.1 ASSESSMENT

a. Safety

Phase I investigation of Still Lake Dam does not indicate conditions which constitute an immediate hazard to human life or property. Based on engineering judgment and the performance of the dam, the project appears to be in fair condition. The project, however, does have inadequacies and deficiencies which, if not remedied, have the potential for developing into hazardous conditions.

Using the Corps of Engineers screening criteria for initial review of spillway adequacy, it has been determined that the spillway is inadequate for all floods in excess of 4 percent of the Probable Maximum Flood. Overtopping of the dam would significantly increase the hazard to loss of life and property, and therefore, the spillway is adjudged as "seriously inadequate" and the dam is assessed as unsafe, non-emergency.

The classification of "unsafe" applied to a dam because of a "seriously inadequate" spillway is not meant to connote the same degree of emergency as would be associated with an "unsafe" classification applied for a structural deficiency. It does mean, however, that based on an initial screening and preliminary computations, there appears to be a serious deficiency in spillway capacity and if a severe storm were to occur, overtopping and failure of the dam could take place, significantly increasing the hazard to loss of life downstream of the dam.

Structural stability analyses based on available information and the visual inspection indicates that the stability of the spillway section against overturning is inadequate for all loading conditions except earthquake, whereas sliding is inadequate for all loading conditions.

b. Adequacy of Information

The lack of in-depth engineering data did not allow for a definitive assessment. Therefore, the adequacy of the dam could not be assessed from the standpoint of reviewing design and construction data, but is based primarily on visual inspection, past performance history and sound engineering judgment.

c. Need for Additional Investigations

The following investigations are required to be performed by a licensed engineer experienced in dam engineering:

1. Investigate the site specific characteristics of the watershed to more accurately determine the hydrologic/hydraulic capabilities of the dam and watershed. Conduct studies to determine what measures are necessary to improve discharge capacities.

2. Determine the exact geometry of the gravity structure and the material properties of the downstream and upstream earth buttress and foundation. Perform an in-depth structural stability analysis.

3. Investigate the seepage condition which exists along the surfaces of the downstream earth buttress, downstream of the buttress, and near the right abutment contact, and to recommend measures to eliminate these conditions.

d. Urgency

The additional required investigations described above must be initiated within 3 months from the date of notification. Within one year of notification, remedial measures as a result of this investigation must be initiated, with completion of these measures during the following year. In the interim, develop an emergency action plan for notification of downstream residents and proper governmental authorities in the event of overtopping and provide around-the-clock surveillance of the dam during periods of extreme runoff. The other deficiencies as reported below must be corrected within one year of notification.

7.2 RECOMMENDED MEASURES

1. The results of the aforementioned in-depth investigations will determine the appropriate remedial measures required.

2. Monitor at biweekly intervals with the aid of weirs and/or other measuring devices, the seepage through and under the dam.


3. Remove vegetation and debris from the surfaces of the downstream earth buttress. Provide a program of periodic cutting and mowing of all embankment surfaces. Inspections should be made to determine if removal and/or cutting of vegetation will adversely affect the condition of the dam.

4. Place riprap or boulders at the toe of the spillway chute to provide proper energy dissipation and prevent erosion and undermining.

5. Provide a program of periodic inspection and maintenance of the dam and appurtenances, including yearly operation and lubrication of the reservoir drain valve and its control facilities. Document this information for future reference. The emergency action plan described in Section 7.1(d) should be maintained and updated periodically during the life of the structure.

DRAWINGS

APPENDIX A



TOPOGRAPHIC MAP
STILL LAKE DAM

PHOTOGRAPHS

APPENDIX B




PHOTOGRAPH 1. CONDITION OF DOWNSTREAM SLOPE OF EARTH BUTTRESS (OBSERVE DEBRIS AND VEGETATION)




PHOTOGRAPH 2. SEEPAGE THROUGH DAM (OBSERVE SWAMP-LIKE VEGETATION AT TOE)



PHOTOGRAPH 3. WET GROUND APPROXIMATELY 40 FEET DOWNSTREAM
OF DAM



PHOTOGRAPH 4. SEEPAGE DOWNSTREAM OF DAM



PHOTOGRAPH 5. CHANNEL DOWNSTREAM AND PARALLEL TO DAM
TO COLLECT SEEPAGE



PHOTOGRAPH 6. SPILLWAY



PHOTOGRAPH 7. CONDITION OF SPILLWAY CHUTE AND DOWNSTREAM CHANNEL



PHOTOGRAPH 8. CONDITION OF BROAD-CRESTED CONCRETE SILL



PHOTOGRAPH 9. AREA DOWNSTREAM OF DAM

VISUAL INSPECTION CHECKLIST

APPENDIX C

VISUAL INSPECTION CHECKLIST

1) Basic Data

a. General

Name of Dam Still Lake Dam
Fed. I.D. # NY01266 DEC Dam No. Unknown
River Basin Lower Hudson River
Location: Town Ossining County Westchester
Stream Name None
Tributary of New Croton Reservoir
Latitude (N) 41° 12.2' Longitude (W) 073° 48.6'
Type of Dam Masonry - Earthfill Buttress
Hazard Category High
Date(s) of Inspection 17 March 81
Weather Conditions Sunny, 55°F
Reservoir Level at Time of Inspection 2.25ft below dam crest

b. Inspection Personnel Mr Harvey Feldman and Mr. Albert DiBernardo

c. Persons Contacted (Including Address & Phone No.)

Mr. Irv Saltzman (914) 762-0041

Ossining, New York 10562

Mr. Barry Shainman (914) 762-1180

Adams Road, Ossining, New York 10562

d. History:

Date Constructed 1930 Date(s) Reconstructed Not

Applicable

Designer Unknown

Constructed By Unknown

Owner Still Water Lake Association

2) Embankment

a. Characteristics

- (1) Embankment Material Earthfill material; had consistency of a silt or sandy silt
- (2) Cutoff Type Unknown, however there is believed to be none
- (3) Impervious Core None
- (4) Internal Drainage System A ^{buried} vitrified clay pipe extends along the downstream toe to the right of the spillway section (facing d/s)
- (5) Miscellaneous No drawings for the dam exist. It appears that the concrete structure is buttressed by an upstream earth buttress as well as a downstream earth buttress; however, the upstream buttress could not be inspected because it was submerged.

b. Crest

- (1) Vertical Alignment The vertical alignment of the concrete wall and the d/s earth buttress is good with no sags or depressions
- (2) Horizontal Alignment The dam contains a dog leg approximately 200ft from the right abutment contact.
- (3) Surface Cracks None were observed along the embankment crest nor the concrete crest
- (4) Miscellaneous None

c. Upstream Slope (Upstream Earth Buttress)

- (1) Slope (Estimate) (V:H) 1:6 (very approx due to submergence)
- (2) Undesirable Growth or Debris, Animal Burrows None was observed.
- (3) Sloughing, Subsidence or Depressions Could not be determined due to submergence of the slope.

(4) Slope Protection None was visible

(5) Surface Cracks or Movement at Toe Unknown

d. Downstream Slope

(1) Slope (Estimate - V:H) 1:2

(2) Undesirable Growth or Debris, Animal Burrows Trees up to 2' ϕ , small sapplings and brush and some debris exist

(3) Sloughing, Subsidence or Depressions None observed

(4) Surface Cracks or Movement at Toe None observed

(5) Seepage Seepage exists along the entire length of the dam, with some locations worse than others. The seepage areas are generally located 20 to 40 ft from the embankment toe. No seepage was observed through the embankment

(6) External Drainage System (Ditches, Trenches; Blanket) Ditches exist, however they were installed by the local landowner to channel the seepage

(7) Condition Around Outlet Structure Generally in good condition with only minor siltation at invert of outlet pipe

(8) Seepage Beyond Toe See note No. (5) directly above. Also it was reported that one house just d/s of the dam has a continually wet basement.

e. Abutments - Embankment Contact

Appear to be free of leaks and does not show signs of instability.

(1) Erosion at Contact None

(2) Seepage Along Contact None

3) Drainage System

a. Description of System A vitrified clay pipe (12" ϕ) collects seepage
through the dam, to the right of the soilway, The pipe was
flowing, and appears to be unclogged. It is unknown whether
an internal drainage system exists.

b. Condition of System See (a.)

c. Discharge from Drainage System A small quantity of flow was
recorded exiting the vitrified clay pipe.

4) Instrumentation (Monumentation/Surveys, Observation Wells, Weirs,
Piezometers, Etc.)

None


5) Reservoir

- a. Slopes The Taconic Parkway Embankment bounds the lake to the west. All slopes appear stable.
- b. Sedimentation The water was relatively clear. Sedimentation does not appear to be a problem.
- c. Unusual Conditions Which Affect Dam None

6) Area Downstream of Dam

- a. Downstream Hazard (No. of Homes, Highways, etc.) A number of summer and year-round homes exist downstream of the dam.
- b. Seepage, Unusual Growth Seepage was observed along the entire length of typically 20 to 40 feet from the toe.
- c. Evidence of Movement Beyond Toe of Dam None
- d. Condition of Downstream Channel The downstream channel is straight for the first 150 ft (approx) d/s of the spillway chute and then is diverted through a constricted stone structure.

7) Spillway(s) (Including Discharge Conveyance Channel)

- The spillway exists approximately 80 feet from the right abutment contact.
- a. General The spillway consists of a broad crested weir with an arched concrete top, i.e.  where $y = 1.5'$ & $x = 9.5'$. The water flows through the weir down an approximate 12 step structure constructed of boulder masonry. Prior to entering the channel, flow is channeled down a concave upward masonry chute.
- b. Condition of Service Spillway The spillway appears to be in good condition, however, ^{concrete} constructions at each side of the weir exist. The surface of the masonry chute was very irregular, either due to erosion or poor construction techniques.

c. Condition of Auxiliary Spillway Not Applicable

d. Condition of Discharge Conveyance Channel The downstream channel is clear of obstructions and in generally good condition It is approx. 6 ft wide and 3ft deep and has rock protected side slopes The channel is relatively straight for the first 150 ft (approx) d/s of the dam

3) Reservoir Drain/Outlet

Type: Pipe ☒ Conduit _____ Other _____

Material: Concrete _____ Metal ☒ Other _____

Size: 2 feet Length Unknown

Invert Elevations: Entrance Unknown Exit Unknown

Physical Condition (Describe): _____ Unobservable _____

Material: Steel, appeared to be in good condition at the outlet

Joints: Unknown Alignment Unknown

Structural Integrity: Flow through the pipe was not permitted since no one could operate the regulating valve.

Hydraulic Capability: Unknown (see above)

Means of Control: Gate _____ Valve ☒ Uncontrolled _____

Operation: Operable _____ Inoperable _____ Other Unknown*

Present Condition (Describe): Unknown

* However, according to Mr. Saltzman, the drain has been operated in the past.

9) Structural

- a. Concrete Surfaces The concrete surfaces appeared to be in good condition with minor bulging occurring at a few locations along the upstream face.
- b. Structural Cracking No major structural cracks were observed
- c. Movement - Horizontal & Vertical Alignment (Settlement) The vertical and horizontal alignment appear good
- d. Junctions with Abutments or Embankments The earth buttress(es) appear to be in good contact with the concrete wall.
- e. Drains - Foundation, Joint, Face None located except for that which was previously mentioned.
- f. Water Passages, Conduits, Sluices None except for the low level outlet previously described.
- g. Seepage or Leakage None

- h. Joints - Construction, etc. Joints were in good condition, with no observable erosion, deterioration, spalling or Leakage occurring
- i. Foundation Unknown
- j. Abutments Not Applicable
- k. Control Gates Not Applicable
- l. Approach & Outlet Channels See previous description on sheet 5.
- m. Energy Dissipators (Plunge Pool, etc.) A 12 step structure for dissipation of flow and masonry chute as previously described.
- n. Intake Structures Not Applicable
- o. Stability Appears to be stable
- p. Miscellaneous None

10) Appurtenant Structures (Powerhouse, Lock, Gatehouse, Other)

a. Description and Condition There are no powerhouse,
lock, gatehouse, or other appurtenant structures
located at the dam site.

HYDROLOGIC DATA AND COMPUTATIONS

APPENDIX D

CHECK LIST FOR DAMS
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA

1

AREA-CAPACITY DATA:

	<u>Elevation (ft.)</u>	<u>Surface Area (acres)</u>	<u>Storage Capacity (acre-ft.)</u>
1) Top of Dam	<u>487</u>	<u>26.3</u>	<u>177 acre-feet</u>
2) Design High Water (Max. Design Pool)	<u>Unknown</u>	<u>Unknown</u>	<u>Unknown</u>
3) Auxiliary Spillway Crest	<u>Not Applicable (N.A.)</u>	<u>N.A.</u>	<u>N.A.</u>
4) Pool Level with Flashboards	<u>N.A.</u>	<u>N.A.</u>	<u>N.A.</u>
5) Service Spillway Crest	<u>486</u>	<u>24.3</u>	<u>150 acre-ft</u>

DISCHARGES

	<u>Volume (cfs)</u>
1) Average Daily	<u>Unknown</u>
2) Spillway @ Maximum High Water	<u>30 cfs</u>
3) Spillway @ Design High Water	<u>Unknown</u>
4) Spillway @ Auxiliary Spillway Crest Elevation	<u>None</u>
5) Low Level Outlet	<u>Unknown</u>
6) Total (of all facilities) @ Maximum High Water	<u>30+ cfs</u>
7) Maximum Known Flood	<u>Unknown</u>
8) At Time of Inspection	<u>None</u>

CREST:

ELEVATION: 486Type: Stone/Masonry Gravity Structure of Unknown DimensionsWidth: 9.5 feet (Sill) Length: 9.5 feet (Sill)Spillover Broad-crested sillLocation 60 feet from left abutment

SPILLWAY:

SERVICE

486UnknownUnknown

AUXILIARY

Elevation Not Applicable (N.A.)Type N.A.Width N.A.

Type of Control

Uncontrolled broad-crested concrete sill Uncontrolled N.A.

Controlled:

Type N.A.
(Flashboards; gate)Number N.A.Size/Length N.A.Invert Material N.A.Anticipated Length
of operating service N.A.30 feet (\pm) Chute Length N.A.Not Applicable Height Between Spillway Crest
& Approach Channel Invert
(Weir Flow) N.A.

HYDROMETEOROLOGICAL GAGES:

Type : NoneLocation: Not Applicable (NA)

Records:

Date - N.A.Max. Reading - N.A.

FLOOD WATER CONTROL SYSTEM:

Warning System: None

Method of Controlled Releases (mechanisms):

Valve and 24" reservoir drain

DRAINAGE AREA: 0.22 square miles

DRAINAGE BASIN RUNOFF CHARACTERISTICS:

Land Use - Type: Residential

Terrain - Relief: Hilly

Surface - Soil: Glacial Till

Runoff Potential (existing or planned extensive alterations to existing
(surface or subsurface conditions)

Unknown

Potential Sedimentation problem areas (natural or man-made; present or future)

Appear to be none

Potential Backwater problem areas for levels at maximum storage capacity
including surcharge storage:

Unknown

Dikes - Floodwalls (overflow & non-overflow) - Low reaches along the
Reservoir perimeter:

Location: None

Elevation: Not Applicable

Reservoir:

Length @ Maximum Pool 1600+ feet (miles)

Length of Shoreline (@ Spillway Crest) 1 mile (miles)

TAMS

Job No. 1579-16

Sheet 1 of 23

Project STILL LAKE DAM INSPECTION

Date April 6 1981

Subject Hydrologic / Hydraulic Computations.

By D.L.C.

Checked by _____

Snyder's Coeff

$$640 C_p \sim 375$$

$$C_T \sim 2. \quad C_p = 0.59$$

$$L = 1.2" = 2600' = 0.49 \text{ miles}$$

$$L_{ch} = .5" = 1000' = 0.19 \text{ miles}$$

$$T_p = 2 \{ (1.40)(0.19) \}^{0.3} = .98 \quad \text{Use } T_p = 0.3333$$

$$T_{PR} = 0.9811 + 0.250(0.3333 - 0.1784) = 0.9811 + 0.0387 = 1.02 \text{ hrs}$$

From Hydrograph 33

All Season 200 sq mile 24 hour PMP \sim 22 inches Zone 1

10 sq mile (point rainfall) Percent Values.

6 hour 111

12 hour 123

24 hour 133

48 hour 142

Initial Loss 2.0"

Constant Loss 0.1

$$\text{Lake Area AS } \frac{1}{1} \text{ of } \frac{1}{1} \text{ D/A} \cdot \left(\frac{2423}{140.5} \right) \times 100 = 17\%$$

EL	L.B. Distance	R.B. Distance	300 ft D/S DAM
500	100	1100	
480	270	850	
474	420	440	
470	430	435	

TAMS

Job No. 1579-16

Sheet 2 of 23

Project STILL LAKE DAM INSPECTION

Date APRIL 6, 1981

Subject HYDRAULIC / HYDROLOGIC COMPUTATIONS

By DIC

Ch'k. by _____

Spillway dimensions

Width 9.5'

Ht below arched walkway

at ends 0.5' at center 1.5'

Max Q at 1.0' \approx 30 cfs

DAM dimensions

Top of dam elevation 487 $C \approx 3.09$ (center line)

Width 540'

SURCHARGE STORAGE COMPUTATIONS

EL	ΔH	Area	Mean Area	Δ Volume	Surcharge Storage	Cumulative
	(ft)	(Ac ²)	(Ac)	(Ac ft)	(Ac ft)	
480	0	27.3			0	150
	4		27.3	109.2		
490	10.0	30.3	34.9	349	109	259
500		39.5			458	608

RATING For Spillway - Assume walkway is washed out.

EL	H	C	Q
486			
487	1	33	39
488		33	89
490		33	251

CAPACITY (AKRE FEET)

600 500 400 300 200 100

500

425

490

485

NO. 11462-17

CAPACITY

STILL LAKE

AREA (AKRES)

20 25 30 35 40 45

Sheet 3 of 23

TAMS

Job No. 1579-16

Sheet 4 of 23

Project STILL LAKE DAM.

Date April 22, 81

Subject HYDROLOGIC / HYDRAULIC COMPUTATIONS

By DLC

Ch'k. by _____

Tail Water Elevation

At Section 300 ft Down stream of Dam

Stream invert ~ 470.

max water level ~ 472.4 P.M.F.

471.7 $\frac{1}{2}$ P.M.F.

Assume Water surface slope same as invert slope

ALL INFORMATION CONTAINED
HEREIN IS UNCLASSIFIED

FIELD HYDROGRAPH PACKAGE (HSC-1)
 DEV SAFETY VERSION JULY 1974
 TEST WHEELS: 100, 100, 100, 100

STILL LAKE DAM PHASE 1 INSPECTION
 PVE ANALYSIS USING VIC-100
 APRIL 1975 1745 1875-75

1	150	1	20	0	0	0	0
2	150	1	20	0	0	0	0
3	150	1	20	0	0	0	0
4	150	1	20	0	0	0	0
5	150	1	20	0	0	0	0
6	150	1	20	0	0	0	0
7	150	1	20	0	0	0	0
8	150	1	20	0	0	0	0
9	150	1	20	0	0	0	0
10	150	1	20	0	0	0	0
11	150	1	20	0	0	0	0
12	150	1	20	0	0	0	0
13	150	1	20	0	0	0	0
14	150	1	20	0	0	0	0
15	150	1	20	0	0	0	0
16	150	1	20	0	0	0	0
17	150	1	20	0	0	0	0
18	150	1	20	0	0	0	0
19	150	1	20	0	0	0	0
20	150	1	20	0	0	0	0
21	150	1	20	0	0	0	0
22	150	1	20	0	0	0	0
23	150	1	20	0	0	0	0
24	150	1	20	0	0	0	0
25	150	1	20	0	0	0	0
26	150	1	20	0	0	0	0
27	150	1	20	0	0	0	0
28	150	1	20	0	0	0	0
29	150	1	20	0	0	0	0
30	150	1	20	0	0	0	0
31	150	1	20	0	0	0	0
32	150	1	20	0	0	0	0
33	150	1	20	0	0	0	0
34	150	1	20	0	0	0	0
35	150	1	20	0	0	0	0
36	150	1	20	0	0	0	0
37	150	1	20	0	0	0	0
38	150	1	20	0	0	0	0
39	150	1	20	0	0	0	0
40	150	1	20	0	0	0	0
41	150	1	20	0	0	0	0
42	150	1	20	0	0	0	0
43	150	1	20	0	0	0	0
44	150	1	20	0	0	0	0
45	150	1	20	0	0	0	0
46	150	1	20	0	0	0	0
47	150	1	20	0	0	0	0
48	150	1	20	0	0	0	0
49	150	1	20	0	0	0	0
50	150	1	20	0	0	0	0
51	150	1	20	0	0	0	0
52	150	1	20	0	0	0	0
53	150	1	20	0	0	0	0
54	150	1	20	0	0	0	0
55	150	1	20	0	0	0	0
56	150	1	20	0	0	0	0
57	150	1	20	0	0	0	0
58	150	1	20	0	0	0	0
59	150	1	20	0	0	0	0
60	150	1	20	0	0	0	0
61	150	1	20	0	0	0	0
62	150	1	20	0	0	0	0
63	150	1	20	0	0	0	0
64	150	1	20	0	0	0	0
65	150	1	20	0	0	0	0
66	150	1	20	0	0	0	0
67	150	1	20	0	0	0	0
68	150	1	20	0	0	0	0
69	150	1	20	0	0	0	0
70	150	1	20	0	0	0	0
71	150	1	20	0	0	0	0
72	150	1	20	0	0	0	0
73	150	1	20	0	0	0	0
74	150	1	20	0	0	0	0
75	150	1	20	0	0	0	0
76	150	1	20	0	0	0	0
77	150	1	20	0	0	0	0
78	150	1	20	0	0	0	0
79	150	1	20	0	0	0	0
80	150	1	20	0	0	0	0
81	150	1	20	0	0	0	0
82	150	1	20	0	0	0	0
83	150	1	20	0	0	0	0
84	150	1	20	0	0	0	0
85	150	1	20	0	0	0	0
86	150	1	20	0	0	0	0
87	150	1	20	0	0	0	0
88	150	1	20	0	0	0	0
89	150	1	20	0	0	0	0
90	150	1	20	0	0	0	0
91	150	1	20	0	0	0	0
92	150	1	20	0	0	0	0
93	150	1	20	0	0	0	0
94	150	1	20	0	0	0	0
95	150	1	20	0	0	0	0
96	150	1	20	0	0	0	0
97	150	1	20	0	0	0	0
98	150	1	20	0	0	0	0
99	150	1	20	0	0	0	0
100	150	1	20	0	0	0	0

Sheet 5 of 10

THIS PAGE IS BEST QUALITY PRINTED
 FROM COPY FURNISHED BY THE

8
 9
 10
 11
 12
 13
 14
 15
 16
 17
 18
 19
 20
 21
 22
 23
 24
 25
 26
 27
 28
 29
 30
 31
 32
 33
 34
 35
 36
 37
 38
 39
 40
 41
 42
 43
 44
 45
 46
 47
 48
 49
 50
 51
 52
 53
 54
 55
 56
 57
 58
 59
 60
 61
 62
 63
 64
 65
 66
 67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100
 101
 102
 103
 104
 105
 106
 107
 108
 109
 110
 111
 112
 113
 114
 115
 116
 117
 118
 119
 120
 121
 122
 123
 124
 125
 126
 127
 128
 129
 130
 131
 132
 133
 134
 135
 136
 137
 138
 139
 140
 141
 142
 143
 144
 145
 146
 147
 148
 149
 150
 151
 152
 153
 154
 155
 156
 157
 158
 159
 160
 161
 162
 163
 164
 165
 166
 167
 168
 169
 170
 171
 172
 173
 174
 175
 176
 177
 178
 179
 180
 181
 182
 183
 184
 185
 186
 187
 188
 189
 190
 191
 192
 193
 194
 195
 196
 197
 198
 199
 200
 201
 202
 203
 204
 205
 206
 207
 208
 209
 210
 211
 212
 213
 214
 215
 216
 217
 218
 219
 220
 221
 222
 223
 224
 225
 226
 227
 228
 229
 230
 231
 232
 233
 234
 235
 236
 237
 238
 239
 240
 241
 242
 243
 244
 245
 246
 247
 248
 249
 250
 251
 252
 253
 254
 255
 256
 257
 258
 259
 260
 261
 262
 263
 264
 265
 266
 267
 268
 269
 270
 271
 272
 273
 274
 275
 276
 277
 278
 279
 280
 281
 282
 283
 284
 285
 286
 287
 288
 289
 290
 291
 292
 293
 294
 295
 296
 297
 298
 299
 300
 301
 302
 303
 304
 305
 306
 307
 308
 309
 310
 311
 312
 313
 314
 315
 316
 317
 318
 319
 320
 321
 322
 323
 324
 325
 326
 327
 328
 329
 330
 331
 332
 333
 334
 335
 336
 337
 338
 339
 340
 341
 342
 343
 344
 345
 346
 347
 348
 349
 350
 351
 352
 353
 354
 355
 356
 357
 358
 359
 360
 361
 362
 363
 364
 365
 366
 367
 368
 369
 370
 371
 372
 373
 374
 375
 376
 377
 378
 379
 380
 381
 382
 383
 384
 385
 386
 387
 388
 389
 390
 391
 392
 393
 394
 395
 396
 397
 398
 399
 400
 401
 402
 403
 404
 405
 406
 407
 408
 409
 410
 411
 412
 413
 414
 415
 416
 417
 418
 419
 420
 421
 422
 423
 424
 425
 426
 427
 428
 429
 430
 431
 432
 433
 434
 435
 436
 437
 438
 439
 440
 441
 442
 443
 444
 445
 446
 447
 448
 449
 450
 451
 452
 453
 454
 455
 456
 457
 458
 459
 460
 461
 462
 463
 464
 465
 466
 467
 468
 469
 470
 471
 472
 473
 474
 475
 476
 477
 478
 479
 480
 481
 482
 483
 484
 485
 486
 487
 488
 489
 490
 491
 492
 493
 494
 495
 496
 497
 498
 499
 500
 501
 502
 503
 504
 505
 506
 507
 508
 509
 510
 511
 512
 513
 514
 515
 516
 517
 518
 519
 520
 521
 522
 523
 524
 525
 526
 527
 528
 529
 530
 5

Sheet 6 of 25

THIS PAGE IS BEST QUOTED FROM

FLOOD HYDROGRAPH PACKAGE (HAC-70)
 DAY SAFETY VERSION JULY 1973
 LAST MODIFICATION 01 APR 78

RUN DATE 01/07/78
 TIME 01:00

THIS PAGE IS BEST QUALITY COPY
 FROM COPY FURNISHED TO DDC

STILL LANE DAM PHASE 1 INSPECTION
 PRELIMINARY DESIGN RECORD
 APRIL 1971 1876 1979-80

JOB SPECIFICATION
 NO. 150
 NAME 20
 DAY 0
 JOPS 3
 AUT 1
 LOCAL 0
 TRACE 0
 IPST 0
 NSTAN 0

MULTI-PLAN ANALYSES TO BE PERFORMED
 PLAN: 1 STAGE 4 LOTUS 1

RTIOS= 1.00 .75 .50 .25

SUB-BASE EROSION CONCENTRATION

1 BASIN RUNOFF

ISTAT	ICOMP	IFLOW	ITYPE	JPLY	JPSI	ISAME	ISTAGE	IAUTO
1	0	0	0	0	0	1	0	0

INVS	IJHC	IAREA	SNIP	TRPCA	TRIPC	RATIO	INCH	ISAME	LOCAL
1	1	.22	0.00	.12	0.00	0.000	0	1	0

SPEED PWS
 0.00 22.00 111.00 123.00 135.00 142.00
 TASC COMPUTED BY THE PROGRAM IS .000

LEOPT	STAIR	OLTRA	RTIOL	FRAM	RTIOL	RTION	STPTL	ENSTE	ALNXY	RTIMP
0.00	0.00	0.00	1.00	0.00	0.00	1.00	2.00	.10	0.00	.000

UNIT HYDROGRAPH DATA
 TYPE 1.00 ONE .59

APPROXIMATE CLARK COEFFICIENTS FROM GIVEN SCAVED CP AND 10 FOR TCR 3.73 AND RT 2.00 INTERVAL

UNIT HYDROGRAPH	14	END-OF-PERIOD	CONTINUED	BASE	1.02	PCJPS	CP	.59	SOLE	1.00
12.	.44	74.	79.	85.	45.	32.	28.	1.	15.	11.
8.	6.	5.	2.	1.	1.	1.	1.	1.	1.	1.

Sheet 7 of 13

Sheet 8 of 25

[illegible]

THIS PAGE IS BEST QUALITY
FROM COPY FURNISHED TO DDC

Sept 10 4-05

50411723

THIS PAGE IS BEST QUALITY PRACTICAL COPY FURNISHED TO DDC

Sept 12012

[illegible]

95:K 927FL 2 15 719. 21 192 4027 1000

PEAK	6 HOUR	24 HOUR	72 HOUR	100% 24 HOUR
CE5	40%	16	50	50
CE6	11	1	2	2
CE7	17	10	20	20
CE8	42	40	50	50
CE9	23	20	25	25
CE10	23	20	25	25
CE11	23	20	25	25
CE12	23	20	25	25
CE13	23	20	25	25
CE14	23	20	25	25
CE15	23	20	25	25
CE16	23	20	25	25
CE17	23	20	25	25
CE18	23	20	25	25
CE19	23	20	25	25
CE20	23	20	25	25
CE21	23	20	25	25
CE22	23	20	25	25
CE23	23	20	25	25
CE24	23	20	25	25
CE25	23	20	25	25
CE26	23	20	25	25
CE27	23	20	25	25
CE28	23	20	25	25
CE29	23	20	25	25
CE30	23	20	25	25
CE31	23	20	25	25
CE32	23	20	25	25
CE33	23	20	25	25
CE34	23	20	25	25
CE35	23	20	25	25
CE36	23	20	25	25
CE37	23	20	25	25
CE38	23	20	25	25
CE39	23	20	25	25
CE40	23	20	25	25
CE41	23	20	25	25
CE42	23	20	25	25
CE43	23	20	25	25
CE44	23	20	25	25
CE45	23	20	25	25
CE46	23	20	25	25
CE47	23	20	25	25
CE48	23	20	25	25
CE49	23	20	25	25
CE50	23	20	25	25
CE51	23	20	25	25
CE52	23	20	25	25
CE53	23	20	25	25
CE54	23	20	25	25
CE55	23	20	25	25
CE56	23	20	25	25
CE57	23	20	25	25
CE58	23	20	25	25
CE59	23	20	25	25
CE60	23	20	25	25
CE61	23	20	25	25
CE62	23	20	25	25
CE63	23	20	25	25
CE64	23	20	25	25
CE65	23	20	25	25
CE66	23	20	25	25
CE67	23	20	25	25
CE68	23	20	25	25
CE69	23	20	25	25
CE70	23	20	25	25
CE71	23	20	25	25
CE72	23	20	25	25
CE73	23	20	25	25
CE74	23	20	25	25
CE75	23	20	25	25
CE76	23	20	25	25
CE77	23	20	25	25
CE78	23	20	25	25
CE79	23	20	25	25
CE80	23	20	25	25
CE81	23	20	25	25
CE82	23	20	25	25
CE83	23	20	25	25
CE84	23	20	25	25
CE85	23	20	25	25
CE86	23	20	25	25
CE87	23	20	25	25
CE88	23	20	25	25

STATION 3, 11th, and 20th

67
 68
 69
 70
 71
 72
 73
 74
 75
 76
 77
 78
 79
 80
 81
 82
 83
 84
 85
 86
 87
 88
 89
 90
 91
 92
 93
 94
 95
 96
 97
 98
 99
 100
 101
 102
 103
 104
 105
 106
 107
 108
 109
 110
 111
 112
 113
 114
 115
 116
 117
 118
 119
 120
 121
 122
 123
 124
 125
 126
 127
 128
 129
 130
 131
 132
 133
 134
 135
 136
 137
 138
 139
 140
 141
 142
 143
 144
 145
 146
 147
 148
 149
 150
 151
 152
 153
 154
 155
 156
 157
 158
 159
 160
 161
 162
 163
 164
 165
 166
 167
 168
 169
 170
 171
 172
 173
 174
 175
 176
 177
 178
 179
 180
 181
 182
 183
 184
 185
 186
 187
 188
 189
 190
 191
 192
 193
 194
 195
 196
 197
 198
 199
 200
 201
 202
 203
 204
 205
 206
 207
 208
 209
 210
 211
 212
 213
 214
 215
 216
 217
 218
 219
 220
 221
 222
 223
 224
 225
 226
 227
 228
 229
 230
 231
 232
 233
 234
 235
 236
 237
 238
 239
 240
 241
 242
 243
 244
 245
 246
 247
 248
 249
 250
 251
 252
 253
 254
 255
 256
 257
 258
 259
 260
 261
 262
 263
 264
 265
 266
 267
 268
 269
 270
 271
 272
 273
 274
 275
 276
 277
 278
 279
 280
 281
 282
 283
 284
 285
 286
 287
 288
 289
 290
 291
 292
 293
 294
 295
 296
 297
 298
 299
 300
 301
 302
 303
 304
 305
 306
 307
 308
 309
 310
 311
 312
 313
 314
 315
 316
 317
 318
 319
 320
 321
 322
 323
 324
 325
 326
 327
 328
 329
 330
 331
 332
 333
 334
 335
 336
 337
 338
 339
 340
 341
 342
 343
 344
 345
 346
 347
 348
 349
 350
 351
 352
 353
 354
 355
 356
 357
 358
 359
 360
 361
 362
 363
 364
 365
 366
 367
 368
 369
 370
 371
 372
 373
 374
 375
 376
 377
 378
 379
 380
 381
 382
 383
 384
 385
 386
 387
 388
 389
 390
 391
 392
 393
 394
 395
 396
 397
 398
 399
 400
 401
 402
 403
 404
 405
 406
 407
 408
 409
 410
 411
 412
 413
 414
 415
 416
 417
 418
 419
 420
 421
 422
 423
 424
 425
 426
 427
 428
 429
 430
 431
 432
 433
 434
 435
 436
 437
 438
 439
 440
 441
 442
 443
 444
 445
 446
 447
 448
 449
 450
 451
 452
 453
 454
 455
 456
 457
 458
 459
 460
 461
 462
 463
 464
 465
 466
 467
 468
 469
 470
 471
 472
 473
 474
 475
 476
 477
 478
 479
 480
 481
 482
 483
 484
 485
 486
 487
 488
 489
 490
 491
 492
 493
 494
 495
 496
 497
 498
 499
 500
 501
 502
 503
 504
 505
 506
 507
 508
 509
 510
 511
 512
 513
 514
 515
 516
 517
 518
 519
 520
 521
 522
 523
 524
 525
 526
 527
 528
 529
 530
 531
 532
 533
 534
 535
 536
 537
 538
 539
 540
 541
 542
 543
 544
 545
 546
 547
 548
 549
 550
 551
 552
 553
 554
 555
 556
 557
 558
 559
 560
 561
 562
 563
 564
 565
 566
 567
 568
 569
 570
 571
 572
 573
 574
 575
 576
 577
 578
 579
 580
 581
 582

1
2
3
4
5
6
7
8

PAGE 10 ENCLOSURE 10
ONLY FURNISHED TO DDD

1
2
3
4
5
6
7
8

44
45
46
47
48

SAFETY OF THE PUBLIC

3-07-68 11:10 800-2 800-9 27:0

Sept 13. 1923

THIS PAGE IS BEST QUALITY PRACTICAL COPY FURNISHED TO DDC

[illegible]

PLAN FLOW AND STORAGE (AND DEPLETION) SUMMARY FOR MULTIPLE PLANNING ECONOMIC COMPUTATIONS

FLUAS IN CUMULATED FROM THE SECOND (SECOND WATER YEAR SECOND)

AREA IN PLANNING WATER (CUMULATED WATER YEAR)

RATIOS APPLIED TO FLOWS

RATIO 1 RATIO 2 RATIO 3 RATIO 4

1.00 .75 .50 .25

AREA

STATION

OPERATION

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

1

2

3

4

5

6

7

8

9

10

11

12

SUMMARY OF DAY SAFETY ANALYSIS

PLAN 1

INITIAL VALUES
 ELEVATION 487.00
 SURFACE 172.00
 OUTLINE 31.00

TOP OF DAM
 487.00
 172.00
 31.00

RATIO OF	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE FC-FT	MAXIMUM CUTOFF CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.00	1.00	102.0	788.0	17.00	40.67	0.00
.75	.75	101.0	535.0	17.00	40.67	0.00
.50	.50	100.0	282.0	17.00	40.67	0.00
.25	.25	99.0	130.0	17.00	40.67	0.00

PLAN 2 STATION 3

RATIO	MAXIMUM FLOW CFS	MAXIMUM STAGE-FT	TIME HOURS
1.00	719.0	472.4	40.67
.75	535.0	472.1	40.67
.50	282.0	471.7	40.67
.25	130.0	471.3	40.67

STABILITY ANALYSIS

APPENDIX E

TAMS

Job No. 1579-16

Project Still Lake Dam : Phase I Inspection

Subject Stability Analysis : Loading Conditions and
Analysis Criteria

Sheet 1 of 17

Date 22 April 81

By A. D.

Ch'k. by JP

LOADING CONDITIONS

Case

Description

I

Normal Loading - Lake Level at Overflow
Section Crest Elevation (El. 486)

II

Normal Loading, as in Case I, with an addition-
al Ice Loading of 5 Kips/L.F. at 0.5 feet
below crest.

III

Unusual Loading, Lake Level at 1/2 PMF
(El. 487.32)

IV

Extreme Loading, Lake Level at Full PMF
(El. 487.52)

V

Unusual Loading, Lake Level as in Case I,
with additional Earthquake loadings for
Zone 2 criterion ($n=0.05$)

STABILITY AND OVERTURNING CRITERIA

Case

Location of Resultant

Shear Friction Factor of Safety

I

middle third

> 3.0

II

middle third

> 3.0

III

middle third

> 3.0

IV

middle third

> 3.0

V

within base

> 1.5

TAMS

Job No. 1579-16

Sheet 2 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analysis: Assumed Geometric and Material Properties

By A.D.

Ch'k. by _____

ASSUMED GEOMETRY AND MATERIAL PROPERTIES

1. The configuration of the spillway section is, as shown, on Figure 1. For stability, the d/s face of the gravity structure was assumed to be 0.7H to 1V.
2. The upstream earth buttress was assumed to have a 1V:6H slope to a distance of 15 ft from the dam and a 1V:1H slope thereafter. (See configuration for Case V).
3. The dam was assumed to be founded on a soil foundation. The shearing resistance between the soil and gravity base is $\tan \phi$, and ϕ was assumed to be 25° with a $c = 1 \text{ kgf}$.
4. The unit weights of the materials were assumed, as follows:

Stone / Masonry : $2.4 \gamma_w$ or 150 lbs/ft^3

Saturated Earth Backfill: $2 \gamma_w$ or 125 lbs/ft^3

Also, the lateral earth pressure coefficient was assumed to be 0.5 for the upstream earth buttress. No passive resistance was assumed at the toe.

5. The arched concrete structure above the overflow crest was excluded from this analysis.
6. Refer to Figure 1 for Assumed Typical Cross Section and Assumed Values of Material Properties.
7. Stability analyses & criteria in accordance with Corps of Engineers recommended guidelines.

TAMS

Job No. 1579-16

Project Still Lake Dam: Phase I Inspection

Subject Stability Analysis


Sheet 3 of 17

Date 22 April 81

By A.D.

Ch'k. by _____

ASSUMED TYPICAL CROSS-SECTION OF OVERFLOW SECTION



* $\delta_w = 0.0624 \text{ K/ft}^3$; δ_{sat} = saturated unit weight of soil; and δ_c = unit weight of concrete

SCALE 1 inch = 4 feet
0 2 4 6 feet

Figure 1
NTS = Not to Scale (where stated)

TAMS

Job No. 1579-16

Project Still Lake Dam Phase I Inspection

Subject Stability Analysis

Sheet 4 of 17

Date 22 April 1981

By A.D.

Ch'k. by _____

COMPUTATION OF STRUCTURE CENTER OF GRAVITY (C of G)

— Weight Computations —

Section	$F'(1)$	$F_r(2)$	B	H	$F'FBH\gamma_w$	
W_1	1.0	2.4	3.5	15	126 γ_w	$\left. \begin{array}{l} \text{Total Weight} = \\ 278.3 \gamma_w \text{ klf} \end{array} \right\}$
W_2	0.5	2.4	9.4	13.5	152.3 γ_w	
	—					

note: (1) F' is a geometric factor, i.e. for a triangle $F' = 0.5$, for a rectangle $F' = 1.0$

(2) F_r is a coefficient multiplied by γ_w (62.4 pcf) to obtain unit weight

Determine Moment Weights About Point O:

$$(a) \bar{x} = \frac{W_1 x_1 + W_2 x_2}{W_1 + W_2 + W_3}$$

where x_i = distance to C. of G. of Section in x-direction

$$= \frac{126 \gamma_w \left(\frac{3.5}{2} \right) + 152.3 \gamma_w \left(3.5 + \frac{9.5}{3} \right)}{126 \gamma_w + 152.3 \gamma_w + 0}$$

$$\bar{x} = 4.44 \text{ feet}$$

$$(b) \bar{y} = \frac{W_1 y_1 + W_2 y_2 + W_3 y_3}{W_1 + W_2}$$

where y_i = distance to C. of G. of Section in y-direction

$$\bar{y} = \frac{126 \gamma_w \left(\frac{15}{2} \right) + 152.3 \gamma_w \left(\frac{15 - 1.5}{2} \right)}{126 \gamma_w + 152.3 \gamma_w + 0}$$

$$\bar{y} = 5.86 \text{ feet}$$

TAMS

Job No. 1579-16

Sheet 5 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analyses: Normal Loading Condition
(Lake level at Spillway Crest)

By A.D.

Ch'k. by _____

CASE 1: NORMAL LOADING CONDITION (Lake Level at Spillway Crest)

ASSUMED TYPICAL CROSS SECTION

SCALE: 1 inch = 5 feet

0 2 4 6 8 10 ft


(Pressure Distributions Not to Scale)

Definitions

W_T = Total Weight of Structure

$P_E(w)$ = At-Rest Earth (Water) Force Along Upstream Face (Ignore Effects of 1V:6H slope)

U = Uplift Force Beneath Spillway



Forces
(Kips/LF)

Moment About A
(Kip-Fect/LF)

$$P_w = 0.5(486 - 471)^2 \gamma_w = 112.5 \gamma_w \rightarrow$$

$$P_E = 0.5(482.5 - 471)^2 (\gamma_{sat} - \gamma_w) = 66.1 \gamma_w \rightarrow$$

$$\Sigma F_H : = 178.6 \gamma_w \rightarrow$$

$$W_T = 278.3 \gamma_w \downarrow$$

$$U = 0.5(13)(486 - 471) \gamma_w = 97.5 \gamma_w \uparrow$$

$$\Sigma F_V : = 180.8 \gamma_w \downarrow$$

$$\overline{P_w} = (112.5 \gamma_w)(5) = 562.5 \gamma_w \downarrow$$

$$\overline{P_E} = (66.1 \gamma_w)(3.83) = 253.2 \gamma_w \downarrow$$

$$\overline{W_T} = 278.3 \gamma_w (13 - 4.44) = 2382.2 \gamma_w \downarrow$$

$$\overline{U} = 97.5 \gamma_w (13 - 4.33) = 845.3 \gamma_w \downarrow$$

TAMS

Job No. 1579-16

Sheet 6 of 17

Project Still Lake Dam - Phase I Inspection

Date 22 April 81

Subject Stability Analysis: Normal Loading Condition (Lake Level at Spillway Crest)

By A.D

Ch'k. by _____

From Previous Table:

$$\Sigma F_H = 178.6 \gamma_w \rightarrow (K/LF)$$

$$\Sigma F_V = 180.8 \gamma_w \downarrow (K/LF)$$

$$\left. \begin{aligned} \Sigma M_{resisting} &= \bar{W}_T = 2382.2 \gamma_w \uparrow (K-Ft/LF) \\ \Sigma M_{opposing} &= \bar{P}_W + \bar{P}_E + \bar{U} = 1661 \gamma_w \downarrow (K-Ft/LF) \end{aligned} \right\} \Sigma (M_r - M_o)^* = 721.2 \gamma_w$$

$$* \Sigma M_{resisting} = \Sigma M_r$$

$$* \Sigma M_{opposing} = \Sigma M_o$$

Location of Resultant at Base

$$\bar{X}_{result} = \frac{\Sigma (M_r - M_o)}{\Sigma F_V} - \frac{B}{3} = \frac{721.2 \gamma_w}{180.8 \gamma_w} - \frac{13}{3}$$

$$\bar{X}_{result} = -0.34 \text{ feet outside middle third.}$$

Shear

Friction Factor of Safety:

$$S.F.F.S. = \frac{\Sigma F_V \tan \phi + cA}{\Sigma F_H} = \frac{(180.8 \gamma_w) \tan 25^\circ + 1(13)}{178.6 \gamma_w}$$

$$S.F.F.S. = 1.63 < 3.0 \quad (\text{No Good})$$

TAMS

Job No. 1579-16

Sheet 7 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analyses: Normal Loading (Lake level at Spillway Crest) with Ice Load

By A.D.


Ch'k. by _____

CASE II - NORMAL LOADING (Lake Level at Spillway Crest) WITH ICE LOAD

ASSUMED TYPICAL CROSS SECTION
SCALE: 1 inch = 5 feet
0 2 4 6 8 10 ft
(Pressure Distributions Not to Scale)

Definitions:

W_T = Total Weight of Structure
 $P_E(w)$ = At-Rest Earth (Water) Force Along Upstream Face (Ignore Effects of 1V:6H Slope)
 U = Uplift Force Beneath Spillway
 P_I = ice load = 5,000 lbs/L.F. OR 80.138w



Force
(Kips/L.F.)

Moment About O
(Kip-Foot/L.F.)

$$P_I = 5 \text{ Kips/L.F.}$$

$$\bar{P}_I = 80.138w \times (486 - 0.5 - 471) = 1161.98w$$

From Page 6 of 17, the summation of forces and moments follows:

$$\Sigma F_H = \Sigma F_H (\text{pg 6 of 17}) + \bar{P}_I = 178.48w + 80.138w = 258.7w \text{ (K/L.F.)}$$

$$\Sigma F_V = \Sigma F_V \downarrow (\text{pg 6 of 17}) = 180.88w \downarrow \text{ (K/L.F.)}$$

$$\Sigma M_{\text{resisting}} = \Sigma M_{\text{resisting}} (\text{pg 6 of 17}) = 2,382 w \uparrow \text{ (K-ft/L.F.)}$$

$$\Sigma M_{\text{opposing}} = \Sigma M_{\text{opposing}} (\text{pg 6 of 17}) + \bar{P}_I = 2,823 w \downarrow \text{ (K-ft/L.F.)}$$

TAMS

Job No. 1579-16

Sheet 8 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analysis: Normal Loading (Lake Level at
Spillway Crest) with Ice Loads

By AD

Ch'k. by _____

Resultant Location:

$$\bar{X}_{\text{result}} = \frac{\Sigma(M_r - M_o)}{\Sigma F_v} - \frac{B}{3}$$

$$= \frac{(2382 - 2823)\gamma_w}{180.8\gamma_w} - \frac{13}{3}$$

$$\bar{X}_{\text{result}} = -6.77 \text{ feet (outside middle third)}$$

Shear

Friction Factor of Safety:

$$S.F.F.S. = \frac{\Sigma F_v \tan \phi + cA}{\Sigma F_h} = \frac{180.8\gamma_w \tan 25^\circ + 1(13)}{258.7\gamma_w'}$$

$$= 1.13 < 3.0 \text{ (No Good)}$$

TAMS

Job No. 1579-16

Sheet 9 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analyses: Unusual Loading (1/2 PMF)

By A.D.

Ch'k. by _____

CASE III: UNUSUAL LOADING (1/2 PMF)

ASSUMED TYPICAL CROSS SECTION

SCALE: 1 inch = 5 feet

0 2 4 6 8 10 ft

(Pressure Distributions Not to Scale)


Definition:

W_T = Total Weight of Structure

$P_E(w)$ = At-Rect Earth (Water) Force Along Upstream Face (Ignore Effects of 1V:6H slope)

U = Uplift Force From a Dam

γ_w =



Determine Uplift Force, Location (\bar{x}_u) and Moment:

Force:

$$u_1 = (487.32 - 471) \gamma_w = 16.32 \gamma_w$$

$$u_2 = (472.7 - 471) \gamma_w = 1.7 \gamma_w$$

$$U = \left\{ \frac{u_1 + u_2}{2} \right\} (13) = 117.1 \gamma_w \uparrow (K/LF)$$

Location:

$$\bar{x}_u = \frac{1.7 \gamma_w \left(\frac{13^2}{2} \right) + \frac{\gamma_w (16.32 - 1.7) (13)^2}{3}}{(1.7) 13 \gamma_w + (16.32 - 1.7) \frac{1}{2} (13) \gamma_w} = \frac{555.4 \gamma_w}{117.1 \gamma_w}$$

$$\bar{x}_u = 4.74 \text{ feet}$$

TAMS

Job No. 1579-16

Project Still Lake Dam: Phase I Inspection

Subject Stability Analysis: Unusual Loading ($\frac{1}{2}$ PMF)

Sheet 10 of 17

Date 22 April 81

By A.D

Ch'k. by _____

Determine P_w Force, Location (\bar{y}_{pw}) and Moment:

Force:

$$p_{w1} = \gamma_w (487.32 - 486) = 1.32 \gamma_w$$

$$p_{w2} = \gamma_w (487.32 - 471) = 16.32 \gamma_w$$

$$P_w = \left\{ \frac{1.32 \gamma_w + 16.32 \gamma_w}{2} \right\} (486 - 471)$$

$$P_w = 132.3 \gamma_w \rightarrow (K/LF)$$

Location:

$$\bar{y}_{pw} = \frac{\gamma_w (486 - 471) \left\{ \frac{1.32 (486 - 471)}{2} + \frac{1}{2} (16.32 - 1.32) \frac{(486 - 471)}{3} \right\}}{\gamma_w (486 - 471) \left\{ (1.32) + \frac{1}{2} (16.32 - 1.32) \right\}}$$

$$\bar{y}_{pw} = 5.37 \text{ feet}$$

$$\text{Moment: } P_w \times \bar{y}_{pw} = 710.5 \gamma_w \text{ (K-ft/LF)}$$

Determine P'_w Force, Location (\bar{y}'_{pw}) and Moment \bar{P}'_w :

Force:

$$P'_w = 0.6 \left\{ (0.5) (472.7 - 471)^2 \gamma_w \right\}$$

$$P'_w = 0.87 \gamma_w \leftarrow (K/LF)$$

Location:

$$\bar{y}'_{pw} = \frac{1}{3} (472.7 - 471)$$

$$y'_{pw} = 0.57 \text{ ft.}$$

$$\text{Moment: } P'_w \times \bar{y}'_{pw} = 0.50 \gamma_w \text{ (K-ft/LF)}$$

TAMS

Job No. 1579-16

Sheet 11 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analysis: Unusual Loading (1/2 PMF)

By A.D.

Ch'k. by _____

Summation OF Forces and Moments:

$$(1) \Sigma F_H: \vec{P}_W + \vec{P}_E - \vec{P}_W' = 132.3 \gamma_w + 66.1 \gamma_w - 0.87 \gamma_w$$

$$\Sigma F_H: 197.5 \gamma_w \rightarrow (K/LF)$$

$$(2) \Sigma F_V: W_T \downarrow - U \uparrow = 278.3 \gamma_w - 117.1 \gamma_w$$

$$\Sigma F_V: 161.2 \gamma_w \downarrow (K/LF)$$

$$(3) \Sigma M_{resisting} \text{ (about O)}: \vec{W}_T + \vec{P}_W' = 2382 \gamma_w + 0.50 \gamma_w$$

$$\Sigma M_{resisting}: 2382.5 \gamma_w \uparrow (K\text{-ft}/LF)$$

$$(4) \Sigma M_{opposing} \text{ (about O)}: \vec{P}_W + \vec{P}_E + \vec{U} = 710.5 \gamma_w + 253.2 \gamma_w + 967.2 \gamma_w$$

$$\Sigma M_{opposing}: 1931 \gamma_w \downarrow (K\text{-ft}/LF)$$

Resultant Location:

$$\bar{x}_{result} = \frac{2382.5 \gamma_w - 1931 \gamma_w}{161.2 \gamma_w} - \frac{13}{3}$$

$$\bar{x}_{result} = -1.53 \text{ ft (outside middle third)}$$

Shear
Friction Factor of Safety:

$$S.F.F.S = \frac{\Sigma F_V \tan \phi + cA}{\Sigma F_H} = \frac{161.2 \gamma_w \tan 25^\circ + 1(13)}{197.5 \gamma_w}$$

$$S.F.F.S = 1.43 < 3.0 \quad (\text{No Good})$$

TAMS

Job No. 1579-16

Sheet 12 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analysis: Extreme Loading (PMF)

By A.D.

Ch'k. by _____

CASE IV: EXTREME LOADING (PMF)

ASSUMED TYPICAL CROSS SECTION

SCALE: 1 inch = 5 feet

0 2 4 6 8 10 ft

(Pressure Distributions Not to Scale)


Definition:

W_T = Total Weight of Structure

$P_E(w)$ = At-Rest Earth (Water) Force Along Upstream Face

(Ignore Effects of 1V:6H slope)

U = Uplift Force Beneath Spillway



Determine Uplift Force, Location (\bar{x}_u) and Moment (\bar{U}):

Force:

$$u_1 = (487.52 - 471) \gamma_w = 16.52 \gamma_w$$

$$u_2 = (473.4 - 471) \gamma_w = 2.4 \gamma_w$$

$$U = \left\{ \frac{u_1 + u_2}{2} \right\} (13) = 123 \gamma_w \uparrow \text{ (K-ft/LF)}$$

Location:

$$\bar{x}_u = \frac{13 \gamma_w \left\{ (2.4) \left(\frac{13}{2} \right) + (0.5) (16.52 - 2.4) \left(\frac{13}{3} \right) \right\}}{13 \gamma_w \left\{ 2.4 + 0.5 (16.52 - 2.4) \right\}}$$

$$\bar{x}_u = 4.82 \text{ LF}$$

TAMS

Job No. 1579-16

Sheet 13 of 17

Project Still Lake Dam: Phase I Inspection

Date 24 April 81

Subject Stability Analysis: Extreme Loading (PMF)

By A.D.

Ch'k. by _____

$$\text{Moment (about 0)} : u(13 - \bar{x}_u) = 998.8 \gamma_w \downarrow$$

Determine P_w Force, Location (\bar{y}_{pw}) and Moment:

Force:

$$P_{w1} = \gamma_w (487.52 - 486) = 1.52 \gamma_w$$

$$P_{w2} = \gamma_w (487.52 - 471) = 16.52 \gamma_w$$

$$P_w = \left\{ \frac{P_{w1} + P_{w2}}{2} \right\} (486 - 471)$$

$$P_w = 135.3 \gamma_w \rightarrow (K/LF)$$

Location:

$$\bar{y}_{pw} = \frac{\gamma_w (486 - 471) \left\{ 1.52 \left(\frac{486 - 471}{2} \right) + \frac{1}{2} (16.52 - 1.52) \left(\frac{486 - 471}{3} \right) \right.}{\gamma_w (486 - 471) \left\{ 1.52 + \frac{1}{2} (16.52 - 1.52) \right\}}$$

$$\bar{y}_{pw} = 5.42 \text{ feet}$$

$$\text{Moment: } P_w (\bar{y}_{pw}) = 733.3 \gamma_w \downarrow (K-ft/LF)$$

Determine P_w' Force, Location (\bar{y}_{pw}') and Moment:

Force:

$$P_w' = 0.6 \left\{ 0.5 (473.4 - 471)^2 \gamma_w \right\}$$

$$P_w' = 1.7 \gamma_w \leftarrow (K/LF)$$

Location:

$$\bar{y}_{pw}' = \frac{1}{3} (2.4) = 0.8 \text{ feet}$$

$$\text{Moment: } P_w' (\bar{y}_{pw}') = 1.4 \gamma_w \uparrow (K-ft/LF)$$

TAMS

Job No. 1579-16

Sheet 14 of 17

Project Still Lake Dam: Phase I Inspection

Date 24 April 81

Subject Stability Analysis (Extreme Loading: PMF)

By A.D.

Ch'k. by _____

SUMMATION OF FORCES AND MOMENTS :

$$(1) \Sigma F_H: \vec{P}_W + \vec{P}_E - \vec{P}_U' = 135.3 \gamma_w + 66.1 \gamma_w - 1.7 \gamma_w$$

$$\Sigma F_H: 199.7 \gamma_w \rightarrow (K/LF)$$

$$(2) \Sigma F_V: W \downarrow - U \uparrow = 278.3 \gamma_w - 123 \gamma_w$$

$$\Sigma F_V: 155.3 \gamma_w (K/LF)$$

$$(3) \Sigma M_{\text{resisting}} (\text{about } O): \vec{W}_T + \vec{P}_W' = 2382 \gamma_w + 1.4 \gamma_w$$

$$\Sigma M_r: 2383.4 \gamma_w \uparrow (K\text{-ft}/LF)$$

$$(4) \Sigma M_{\text{opposing}} (\text{about } O): \vec{P}_W + \vec{P}_E + \vec{U} = 733.3 \gamma_w + 253.2 \gamma_w + 998.8 \gamma_w$$

$$\Sigma M_o: 1985.3 \gamma_w \downarrow (K\text{-ft}/LF)$$

Location of Resultant :

$$\bar{X}_{\text{result}} = \frac{\Sigma (M_r - M_o)}{\Sigma F_V} - \frac{B}{4} = \frac{398.1 \gamma_w}{155.3 \gamma_w} - \frac{13}{4}$$

$$\bar{X}_{\text{result}} = -0.69 \text{ ft. (outside middle half)}$$

Shear

Friction Factor of Safety

$$SFFS = \frac{\Sigma F_V \tan \phi + cA}{\Sigma F_H} = \frac{155.3 \gamma_w \tan 25^\circ + 1(13)}{199.7 \gamma_w}$$

$$SFFS = 1.40 < 3.0 \quad (\text{No Good})$$

TAMS

Job No. 1579-16

Sheet 15 of 17

Project Still Lake Dam: Phase I Inspection

Date 22 April 81

Subject Stability Analysis: Unusual Loading: Normal
Pool w/ Earthquake

By A.D.

Ch'k. by _____

CASE V: UNUSUAL LOADING: NORMAL
POOL WITH EARTHQUAKE

ASSUMED TYPICAL CROSS
SECTION

SCALE: 1 inch = 5 feet

0 2 4 6 8 10 ft

(Pressure Distributions Not to
Scale)

Definition:


W_T = Total Weight of Structure

$P_E(w)$ = At-Rest Earth (Water) Force
Along Upstream Face

(Ignore Effects of IV 6 H Slope)

U = Uplift Force Beneath

Spillway



Determine Dynamic Force

Water Force (P_{eq})

Zone 2, $n = 0.05$

Zangar's Coefficient $C = 0.726$ when $\theta = 0$

$$P_{eq} = 0.726 \times 0.05 \times \gamma_w \times (486 - 482.5)^2 = 0.44 \gamma_w \rightarrow (K/ft)$$

$$M_{Peq} \text{ (about Pt. O)} : P_{eq} \times \{ (482.5 - 471) + 0.4(486 - 482.5) \} = 5.78 \gamma_w \rightarrow (K-ft)$$

Inertia Force (nW_T)

$$nW_T = 0.05 (278.3 \gamma_w) = 13.9 \gamma_w \downarrow (K/ft)$$

$$M_{nWT} = 13.9 \gamma_w (5.86) = 81.5 \gamma_w \downarrow (K-ft/ft)$$

TAMS

Job No. 1579-16

Project Still Lake Dam: Phase I Inspection

Subject Stability Analysis: (Unusual Loading: Normal Pool with Earthquake)


Sheet 16 of 17

Date 27 April 81

By AD

Ch'k. by _____

Determine Inertia Force of Upstream Slope Assuming Following Geometry of slope



COMPUTATION OF WEIGHTS

Section	F'	F _y	B	H	F'F _y BHδ _w
1	0.5	2.0	15	25	38 δ _w
2	1.0	2.0	15	9	270 δ _w
3	0.5	2.0	9	9	81 δ _w

$$\left. \begin{array}{l} 38 \delta_w \\ 270 \delta_w \\ 81 \delta_w \end{array} \right\} W_{TE} = 389 \delta_w (4.4)$$

$$n = 0.05$$

$$\therefore nW_{TE} = 19.5 \delta_w (K/LF)$$

Find location of C of G. of Up Earth Buttress:

$$\bar{y} = \frac{38 \delta_w (9 + \frac{2.6}{3}) + 270 \delta_w (\frac{9}{2}) + 81 \delta_w (\frac{9}{3})}{38 \delta_w + 270 \delta_w + 81 \delta_w}$$

$$\bar{y} = 4.71 \text{ feet}$$

$$M_{WTe} = nW_{TE}(\bar{y}) = (19.5 \delta_w)(4.71) = 91.8 \delta_w (K \cdot ft/LF)$$

TAMS

Job No. 1579-16

Sheet 17 of 17

Project Still Lake Dam: Phase I Inspection

Date 24 April 81

Subject Stability Analysis: (Unusual Loading - Normal Pool with Earthquake)

By AD

Ch'k. by _____

Summation of Forces and Moments

$$(1) \Sigma F_H: 178.6 \gamma_w + \vec{P}_{eq} + n\vec{W}_T + n\vec{W}_{TC} = 212.4 \gamma_w \rightarrow (K/LF)$$

$$(2) \Sigma F_V: 180.8 \gamma_w \downarrow \text{ (From pg. 5 of 17) } (K/LF)$$

$$(3) \Sigma M_{resist}: 2382 \gamma_w \uparrow \text{ (From pg. 5 of 17) } (K-ft/LF)$$

$$(4) \Sigma M_{oppo}: 1,661 \gamma_w + \vec{M}_{PEQ} + \vec{M}_{nWT} + \vec{M}_{nTE}$$

$$M_{oppo} = 1840 \gamma_w \downarrow (K-ft/LF)$$

Location of Resultant:

$$\bar{x}_r = \frac{\Sigma (M_r - M_o)}{\Sigma F_V} = \frac{542 \gamma_w}{180.8}$$

$$\bar{x}_r = 2.99 \text{ within base. OK}$$

Shear Friction Factor of Safety:

$$SFFS = \frac{\Sigma F_V \tan \phi + cA}{\Sigma F_H} = \frac{180.8 \gamma_w \tan 25 + 1(13)}{212.4 \gamma_w}$$

$$SFFS = 1.37 < 1.5 \quad \text{NG.}$$

REFERENCES

1. J. H. H. H.

REFERENCES

1. "Flood Hydrograph Package (HEC-1) Users Manual for Dam Safety Investigations", U.S. Army Corps of Engineers, Hydrologic Engineering Center, September 1979.
2. "Seasonal Variation of the Probable Maximum Precipitation, East of the 105th Meridian for Areas from 10 to 1,000 Square Miles, and Durations of 6, 12, 24 and 48 Hours", Hydrometeorological Report No. 33. Weather Bureau, U.S. Department of Commerce, April 1956.
3. "Recommended Guidelines for Safety Inspection of Dams", Department of the Army, Office of the Chief of Engineers, Appendix A.
4. "New England Lizard Section", Internal Report, Civil Engineering Department, Purdue University, West Lafayette, Ind., 1962.
5. Geological Survey of New York, "The University of the State of New York, The State Education Department", Map and Chart Series No. 5, Albany, New York, 1962.

**DATA
FILM**